

Important Notice

Procedure/Safeguard Measures adopted to check Radiation at a leading Casting Exporter's Manufacturing Suppliers Premises and Warehouse

At Suppliers premises/Manufacturing Foundries-Facilities :

1. All incoming materials entering the gate are checked for radiation thoroughly and logged.
2. All Castings after Fettling are 100% Checked before sending to Finishing Area - There is a dedicated team for this Control Point.
3. All other areas in the manufacturing facilities like raw material storage areas, finishing area, machining areas, painting area, etc. are patrol checked once a day by a Handheld Radiation Pager/Meter and logged.
4. All outgoing materials including finished Castings leaving the Foundry for the Warehouse are checked at the Gate for Radiation thoroughly and logged.

Procedure followed at a leading Exporter Company's Warehouse

1. All incoming materials including the Empty Containers entering the Warehouse Gate are checked for Radiation thoroughly by Handheld Radiation Pager/Meter and logged.
2. All the prominent areas in the Warehouse like finished material storage area/bay, stores, packing area, packing materials, painting area, are patrol checked once a day with Handheld Radiation Pager/Meter and logged - One technical person is totally dedicated for this control.
3. The packed crates/pallets are checked thoroughly and these crates are marked with a Blue Colour Code Paint and logged.
4. Finally the Loaded Container with Blue Colour Coded Crates is thoroughly checked all around after it is sealed by Customs Seal and logged.
5. A Third Party Independent Surveyor also checks the Empty Container before stuffing, then checks each Blue Marked packed crate while entering the container and the stuffed container with his own Calibrated Radiation Meter and if No Radiation Detected, issues a certificate of Radiation Clearance to the Exporter - See Copy of Certificate "I", and which is submitted to the Shipping Co. while issuing the Bills of Lading and the Shipping Co. mentions about this Pre-Scanning for Radiation and NO RADIATION DETECTED Clause on their Bills of Lading along with Third Party Independent Inspecting Cos. Certificate Nos. which is issued to the Exporter and the Shipping Cos. also files a Manifest showing this clause.
6. All outgoing materials including the Loaded Containers leaving the Warehouse Gate are checked for Radiation Thoroughly by Handheld Radiation Pager/Meter and logged.