

Trade Enquiries



Colombia

(Source : EEPC Chicago Office)

<i>Name of the Company</i>	<i>Addresses</i>	<i>Contact Person/Tel./Fax/E-mail</i>	<i>Items interested</i>
Innovateq S.A.	Bogota Colombia	Attn. : Mr. German Alvarez Tel. : (57) 1 658 1400 E-mail : galvarez@bosch.com.co	Ball joints, steering linkages, track control and suspension arms and stabilizer links, clutches, shock absorbers, water pumps and other car parts.

Germany

(Source : EEPC Duesseldorf Office)

Techzinkunig Ltd.	Merzinger Str. 23 40476 Dusseldorf Germany	Attn. : Mr. Kunle Leye Tel. : +49 211 2096841 HP : +49 (0) 178 4039730 E-mail : kunleye75@yahoo.de	Piston rings for trucks.
-------------------	--	---	--------------------------

USA

(Source : EEPC Chicago Office)

Lakeside Sales, Ltd.	1405, 16th Street, Suite 4029 Racine, WI 53403 USA	Attn. : Mr. Lucien Osborne Tel. : 1-(262)-619-0100 Fax : 1-(262)-619-0300 E-mail : losborne@wi.rr.com	- S-hooks of carbon steel cold rolled, zinc plated with/without SS gate spring. (Drawings and specifications can be obtained from any of the EEPC offices in India). - Shaft bushing. (Drawings and specifications can be obtained from any of the EEPC offices in India).
Patel International Inc.	30 N River Road Ste 102 Des Plaines, IL 60016 USA	Attn. : Mr. Samir Patel Tel. : 847-795-3006 E-mail : spatel@patelintl.com	Ball joints. (Drawings can be obtained from any of the EEPC offices in India).
Pyramid Mouldings	300 S. Magnolia Ave. Green Cove Springs, FL 32043 USA	Attn. : Mr. Tom Logue Engineering Vice President Tel. : 904-284-5611 Ext. 156 Fax : 904-284-5933 E-mail : tomlogue@pyramidmouldings.com Website : www.pyramidmouldings.com	Dies for piercing, forming, and trimming light gage metal parts (typical thickness id. .030" to .090"). The largest are about 18" by 48" and the smallest are 6" by 6".
S & N International Inc.	821, High Ridge Ct. Darren, IL 60561 USA	Attn. : Mr. Paul Singh President Tel. : 630-663-1526 Fax : 630-663-1527 E-mail : paul@usain.com singh1909@aol.com paul@unitedsecurityapplications.com	Construction related items, light fixtures etc.
Keraro Investments Ltd.	3717 se 3rd St. Des Moines Iowa 50315 USA	Attn. : Sir John S. Robinson Director Tel. : 515-288-9377 Fax : 515-288-9604 E-mail : keraroinvestments@hotmail.com	Ethanol plants, machinery, brick making machines.



Ecuador

(Source : EEPC Chicago Office)

M/s. Imp. Com. Lartizco Cia. Ltda., Sevilla 1-34 y Av. España, Cuenca, Ecuador, Tel. : 593-7-2860498/2809061, Fax : 593 7-2862495/2862240, E-mail : lartizco@etapaonline.net.ec, lartizco@lartizco.com (Attn. : Mr. Aurelio Ortiz C., General Manager - Comercial Lartizco) are interested to import spare parts for passenger car, pick up, light truck as per following specification :

Description	Reference	Description	Reference
CAPOT P DATSUN PICK UP 1,2 73	DS20012A	GUARDAFANGO P TOYOTA STOUT 79 IZQUIERDO	TY10005AR
CAPOT DATSUN 1500	DS20004A	MASCARILLA P GRAN BLAZER CROM 94	CV07077GA
CAPOT P ISUZU 2,3CC 98	IZ20008A	MASCARILLA P ISUZU PICK UP 2,3 94/96	IZ07033GA
CAPOT P MAZDA B2000 88/97	MZ20006A	MASCARILLA P ISUZU PICK UP 2,3 94/96	IZ07034GB
CAPOT P NISSAN SENTRA B13 92	DS20042A	MASCARILLA P ISUZU PICK UP 2,3 96/97	IZ07045GA
CAPOT P SUZUKI FORSA 88/91	CV20021A	MASCARILLA P MAZDA B2000 88/94	MZ07015GA
CAPOT P SUZUKI FORSA SWIFT 91	SZ20006A	MASCARILLA P MAZDA B2000 94/96	MZ07039GA
CAPOT P TOYOTA STOUT 2000 79/97	TY5330189115	MASCARILLA P MAZDA B2000 B2600 97	MZ07054GA
GUARDA CHOQUE P CROMADO C-10 92	CV40039A	MASCARILLA TOYOTA HILUX 74/78	TY07001GAL
GUARDA CHOQUE P MITSUBISHI L200 92	MB04033BA	MASCARILLA TOYOTA HILUX 74/78 CROMADA	TY07001GAR
GUARDA CHOQUE P NISSAN SENTRA B13 92	DS04088BA	MASCARILLA MAZDA 1600/75	MZ07038GA
GUARDA CHOQUE P SUZUKI SWIFT FORSA 92	SZ04007BA	MASCARILLA MAZDA 1600/	MZ07003GB
GUARDA CHOQUE P SUZUKI VITARA 3P 92/95	SZ04011BA	MASCARILLA DARSUN 1200 FARO REDONDO	DS07067GA
GUARDA CHOQUE POST P SWIFT 92/95	SZ04014BA	MASCARILLA DARSUN 1200 FARO CUADRADO	DS07045GA
GUARDA CHOQUE POST P SUZUKI V 92/95	SZ04017BA	MASCARILLA DATSUN 120Y/79	DS07007GA
GUARDAFANGO P CHEVROLET C10 BLAZER 92	CV10038AR	MASCARILLA NISAN SENTRA	DS07105GA
GUARDAFANGO P CHEVROLET C10 BLAZER 92	CV10038AL	MASCARILLA DATSUN 1500	DS07004GA
GUARDAFANGO P DATSUN 1,3-1,5 72/79	DS10007AL	MASCARILLA DATSUN 1800	DS07011GA
GUARDAFANGO P DATSUN 1,3-1,5 72/79	DS10007AR	MASCARILLA ISUZU 76/80	IZ07002GB
GUARDAFANGO P DATSUN PICK 1,2 73	DS10020AR	MASCARILLA TROOPER FARO CUADRADO	IZ07018GB
GUARDAFANGO P DATSUN PICK 1,2 73	DS10020AL	MASCARILLA MITSUBISHI L200	MB07060GA
GUARDAFANGO P IZUSU PICK 2,3 88/97	IZ10007AL	PUERTA DELANTERA P DATSUN 1,2 74 DERECHA	DS80011AR
GUARDAFANGO P IZUSU PICK 2,3 88/97	IZ10007AR	PUERTA DELANTERA P TOYOTA STOUP 79	TY8002AR
GUARDAFANGO P IZUSU PICK 2,3 98	IZ10012AR	PUERTA DELANTERA P TOYOTA STOUP 79	TY8002AL
GUARDAFANGO P IZUSU PICK 2,3 98	IZ10012AL	PUERTA P MAZDA 323 DERCHA	MZ07004HAR
GUARDAFANGO P NISAN SENTRA	DS10063AR	PUERTA P MAZDA 323 IZQUIERDA	MZ07004HAL
GUARDAFANGO P TOYOTA HILUX 4X2 2001	TY10135CR	PUERTA P MAZDA 1600 DERECHA	MZ07038HAR
GUARDAFANGO P TOYOTA STOUT 79 DERCHO	TY10005AL	PUERTA P MAZDA 1600 IZQUIERDA	MZ07038HAL
		PUERTA P ISUZU 76/80 DERECHA	IZ07002HAR
		PUERTA P ISUZU 76/80 IZQUIERDA	IZ07002HAL

Singapore

(Source : EEPC Singapore Office)

M/s. PMK Private Limited, 10 Anson Road, Hex 22-08, International Plaza, Singapore 079903, Tel. : (65) 62216233, Fax : (65) 62255964, E-mail : pmk2208@singnet.com.sg (Attn. : Mr. Choi Dong Moo, Managing Director) are interested to import the following items :

- Bolster coil spring No. 73 – 320 sets
Drawing No. : C & W-S 9867 RG-B
Bolster coil spring No. 73 (outer, middle & inner) to Drawing No. C & W-S 9867 RG-B, to be manufactured to JIS specification G 4801 and material shall be SUP 9A, hardened in oil and suitably tempered.
- Axle coil spring No. 74 – 640 sets
Drawing No. : C & W-S 9869 RG-B
Axle coil spring No. to 74 Drawing No. C & W-S 9869 RG-B, to be manufactured to JIS specification G 4801 and material shall be SUP 9A, Hardened in oil and suitably tempered.

- Wheel steel solid – 1200 nos.
Wheel steel solid forged with wheel bore rolling dimension of rough turn for 4-5/8" dia. Wheel shall be manufactured in accordance with JIS specification E 5402 class 2. Material shall be SSW - Q2S to Drawing No. W 770 (Annexure 1).
- Parallel axle type "Y" – 600 nos.
Parallel axle type "Y" shall be manufactured in accordance with JIS specification E 5402 class 2. Material shall be SFA 60A to Drawing No. C & W-45 10324 BTC-C (Annexure 2).

(Drawings can be obtained from any of the EEPC Offices in India).